USAEC

Hole No. C0516

Collar Elev 6906

Total Depth 103.7

Date:

Beg ____ Fin. _____

Location:

Claim _____

Dist. _____

Coord's 47,112N-201,800E

Logged by _____

60.3 / 90.7 Recovery 66.5 %



No core recovered

13.0

GyMs.spts

> CaCO3A

SS; VF-F; LGy-LBr-DR; BdgP; Ms; DR-LGy, spts

RMSspts

26.0

SS; F; LR-LGy; BdgN

RGyMSSm-Fks

RMSspt

37.2

38.7

SS; VF-F; LR-MR; BdgP; Ms, DR, Sms, Spts.

SS; F; LR-LGy; BdgN-P

43.0

> R-GnMS Fks-Gls.

SS; F; LR-LGy; BdgN. Platy(ntd); Ms-Sts; DR, Sms, Spts, Fks.

> Platy

RStsSpt.

RMSspts

58.5

SS; F; LR-LGy-LBr; BdgN-P Ms, DR-LGyGn, Fks, Sms, Gls. Lim S; CaCO3A(ntd.

RGyMsGls

> R-GnGy-MsGls

RMSSm

> CaCO3A

73.7

> CaCO3A

RMSSm.

SS; F; LR-LGy-LBr; BdgN

> BrColor.

79.4

> RStsSpt.

> RStsSpt

> RMSSms.

RMSspt.

RMSspt.

SS; F; LR-LGy-DR(ntd; BdgP-N; Ms-Sts, DR, Spts, Sms, Fks; Lim S.

RMSspt.

> MRcolor

94.5

SS; F-M; DR-MR; BdgN.

103.7

Finis

GPO—D—FSO—Peerless Printing Co., Denver, Colo.