USAEC

Hole No. Co 126

Collar Elev 6873

Total Depth 73'

Date:

Beg 4-12-51 Fin. 4-12-51

Location:

Claim V. O. M.

Dist. Cove Mesa

Coord's N 48 202 E 201 057

Logged by Coppedge

Recovery 59.5 %



	lbs	oz
MS in SS. MS + SS WH.	3	8
MS Green.		
MS in SS. MS + SS WH.	5	10
MS Brown.		
MS WH + LT Gy.	7	8
MS WH + LT Green.		
MS in SS. MS WH + SS TAN.	6	4
SS WH. V.F.		
MS in SS. MS + SS TAN.		
SS WH. V.F.	7	0
SS V. RR TAN. V.F.		
SS WH. V.F.	8	8
MS Green + Brown.		
MS Brown.		
MS in SS. MS + SS LT TAN.		
MS Green.	5	0
MS Brown.		
MS in SS. MS + SS LT Rd.		
MS in SS. MS. Green + Rd. SS TAN.		
MS in SS. MS + SS WH.	5	4
MS. Brown		
SS WH. V.F.		
MS in SS. MS Brown + WH. SS. TAN. F.	6	2
MS Brown.		
MS Brown + Green.		
MS in SS. MS + SS LT TAN.		
MS DK Rd.		
MS in SS. MS + SS WH.	5	2
MS Brown.		
MS in SS. MS Green + WH. SS WH. V.F.		
MS Rd.		
MS in SS. MS WH + Rd. SS TAN.	5	10
SS PNK. V.F.		
SS WH. V.F.		
MS Brown.	6	10
SS WH. V.F.		
MS DK Rd.		
MS in SS. MS WH + SS PNK.		
SS PNK. V.F.	5	12
SS Rd. V.F.		
SS PNK. F.	6	14
SS WH. V.F.		
SS LT TAN V.F.		
SS WH. V.F.	4	15

GPO—D—FSO—Peerless Printing Co., Denver, Colo.