

Hole No. L 055

Collar Elev _____

Total Depth 225.0

Date: _____

Beg _____ Fin. _____

Location: _____


Claim _____

Dist. _____

Coord's _____

Logged by WJW

Recovery _____ %



196.9 - Bluff contact.

F-N; LBRR; Bdg N; Friable. Lim. S.

Mass split (Marlim stains)

CaCO₃ A (Fines Grained ss (0.2))

208.6

6.6
10.0

F; L - DR (Mottled); Bdg N. Ca CO₃ S. Lim S.

8.0
10.0

M.S. R. Seams.

225.0

Finish