

USAEC

Hole No. A 10

Collar Elev. 5600.35

Total Depth 15'

Date:

Beg. 5-4-52 Fin. 5-4-52

Location:

Claim _____

Dist. Agatha

Coord's _____

Logged by V. D. S.

Recovery 64 %

| Recovery | Color | Bedding | Texture | Grain Coating | Carbon | DR Minerals |
|----------|-------|----------|---------|---------------|--------|--------------|
| 0 | | | | | | 0-5 Plug |
| 3.3 | | | | | | |
| 5.0 | Br | T xbd | CSs | lim | | S clay Gls |
| 10 | | | | | | |
| 3.1 | DR | T xbd | M-CSs | lim | | S clay Gls |
| 5.0 | DR | thin lam | silt | lim | | base Ks 11.3 |
| 20 | | | | | | |
| 30 | | | | | | |
| 40 | | | | | | |
| 50 | | | | | | |
| 60 | | | | | | |
| 70 | | | | | | |
| 80 | | | | | | |
| 90 | | | | | | |
| 100 | | | | | | |
| 110 | | | | | | |
| 120 | | | | | | |
| 130 | | | | | | |
| 140 | | | | | | |
| 150 | | | | | | |
| 160 | | | | | | |
| 170 | | | | | | |
| 180 | | | | | | |
| 190 | | | | | | |
| 200 | | | | | | |