

USAEC

Hole No. A 13

Collar Elev. 5608.2

Total Depth 35.0

Date:

Beg. _____ Fin. _____

Location:

Claim _____

Dist. _____

Coord's _____

Logged by _____

Recovery 78.3 %

| Recovery | Color | Bedding | Texture | Grain Conting | Carbon | Other Minerals |
|----------|-------|---------|---------|---------------|--------|-------------------|
| 0 | | | | | | 0-5 Plug |
| 2.0 | Gy | T | Ms | | | |
| 7.0 | | | | | | |
| 10 | | | | | | |
| 3.5 | Gy | Tan | Ms | | | |
| 5.0 | BR | Xbd | MSS | lim | | |
| 6.0 | | | | | | |
| 20 | BR | | | | | A clay Gls at 18' |
| 6.0 | | T | MF | lim | | |
| | | Xbd | SS | | | A clay Gls at 20' |
| 7.0 | | | | | | |
| 7.0 | BR | | | | | A clay Gls at 23' |
| 30 | | | | | | |
| 5.0 | Gy | Tan lam | Ms | | | Base RS 27.2 |
| 5.0 | DR | Tan lam | Silt | lim | | A Mn dendrites |
| 5.0 | | | | | | |
| 40 | | | | | | |
| 50 | | | | | | |
| 60 | | | | | | |
| 70 | | | | | | |
| 80 | | | | | | |
| 90 | | | | | | |
| 100 | | | | | | |
| 110 | | | | | | |
| 120 | | | | | | |
| 130 | | | | | | |
| 140 | | | | | | |
| 150 | | | | | | |
| 160 | | | | | | |
| 170 | | | | | | |
| 180 | | | | | | |
| 190 | | | | | | |
| 200 | | | | | | |

23.5
30